

Janzen, Heather

From: City Council
Subject: FW: Email - Communication - Carey Blatchford - Housing Accelerator Fund - CK 750-1
Attachments: June 24th HAF.docx; gt_PipeLogix Report.pdf

From: Web NoReply <web-noreply@Saskatoon.ca>
Sent: Monday, June 24, 2024 4:26 PM
To: City Council <City.Council@Saskatoon.ca>
Subject: Email - Communication - Carey Blatchford - Housing Accelerator Fund - CK 750-1

--- Replies to this email will go to [REDACTED] ---

Submitted on Monday, June 24, 2024 - 16:24

Submitted by user: [REDACTED]

Submitted values are:

I have read and understand the above statements.: Yes

I do not want my comments placed on a public agenda. They will be shared with members of Council through their online repository.: No

I only want my comments shared with the Mayor or my Ward Councillor.: No

Date: Monday, June 24, 2024

To: His Worship the Mayor and Members of City Council

Pronouns: She/her/hers

First Name: Carey

Last Name: Blatchford

Phonetic spelling of first and/or last name: [REDACTED]

Email: [REDACTED]

I live outside of Saskatoon: No

Saskatoon Address and Ward:

Address: [REDACTED] Kirk Cres

Ward: Ward 8

What do you wish to do ?: Submit Comments

What meeting do you wish to speak/submit comments ? (if known):: HAF Public Hearing

Comments:

Please see attached letter and supporting sewage infrastructure documents as to why I oppose the HAF proposal.

Attachments:

- [June 24th HAF.docx](#)14.35 KB
- [gt_PipeLogix Report.pdf](#)332.63 KB

Will you be submitting a video to be vetted prior to council meeting?: No

June 24th

To City Council,

I live in Greystone Heights neighborhood, and we have many issues with the current sewage infrastructure. The Planning and Development Committee shared that they had a high-level analysis completed to determine that sewage infrastructure could handle densification. While I'm pleased to see that an analysis had been completed in 2022, I am disappointed to see that Development and Planning has lied to you and us when they stated that there was nothing to report and everything is good to go.

In general, the infrastructure of the 64-year-old pipes is in ok shape... if you consider multiple cracks, fractures, and breaks a high-quality standard capable of withstanding densification.

Upon further review of the analysis, the survey between 7746 and 7747 indicates an offset pipe which is a significant concern and will cause major problems. There has been no indication that these pipes have been repaired to date. Considering that this is just a review of one Crescent's sewage infrastructure I would surmise that there are many issues in the HAF proposed development areas that are also in disrepair and be reported upon. Furthermore, has the Planning and Development Committee taken into consideration that these pipes may not be able to handle additional flow from rainwater that ends up in the sewer causing issues in backflow? Reviewing these reports, I would doubt it.

Even if the sewage infrastructure was top notch according to 2011 Urban planning of sewer infrastructure research report by Roux, Mur, Risch & Boutin "Among the various parameters that affect the environmental performances of the sewer network, the housing density is indeed the main one, up to a factor of about 10 between a dense city and a scattered one." In reviewing previous minutes of the SPC Environment, Utilities and Corporate Services meetings, I could not find one discussion that considered the current sewage infrastructure, and the possible negative environmental impacts densifying Saskatoon has on Saskatchewan rivers, streams and lakes. Is it appropriate to maybe decrease our carbon footprint (as you will see in my next point) while increasing the pollution of our waters?

You need to leave Kirk Crescent and Greystone Heights out of the densification plans.

Respectfully,

Carey Blatchford
■ Kirk Crescent

Tabular Report of PSR 8823

for City of Saskatoon

Setup	47	Surveyor	AP	Certificate#	U-0620-70309622	System Owner	C of S
Drainage	Survey Customer: C of S						
P/O #	Date	2022/11/25	Time	10:40	Street	Kirk Cres	
City	Saskatoon	Further location details					
Up	7747	Rim to invert	Grade to invert	Rim to grade	M		
Down	3089	Rim to invert	Grade to invert	Rim to grade	M		
Use	Sanitary	Direction	Down	Flow control	Media No		
Shape	Circular	Height	200	Width	mm	Preclean	J
Material	Clay Tile	Joint length	M	Total length	86.0	M	Length Surveyec
Lining		Year laid	1960	Year rehabilitated			Weather
Purpose		Cat					Pressure
Additional info	Counter reading 108m Should be 86m.				Structural	O & M	Constructional
Location					Miscellaneous		
Project	Sanitary CCTV			Work Order			
Northing	Easting			Elevation			
Coordinate System				GPS Accuracy			

Count	Video	CD Code	In1	In2	%	JntFr	To	ImRef	Remarks
0.0		ST Start of Survey							
0.0		AMH Manhole							7747
0.0		MWL Water Level			0				
3.7		MMC Material change							VCT
3.9		CS Crack Spiral				J 05 08			
5.6		DAE Deposits Attached Encrustation			5	J 08 04			
6.5		MWL Water Level			5				
6.6		DAE Deposits Attached Encrustation			5	J 07 03			
9.2		CS Crack Spiral				J 10 12			
9.3		FC Fracture Circumferential				01 11			
9.4		TBI Tap Break-in Intruding	100	10		12			
10.1		DAE Deposits Attached Encrustation			5	J 08 03			
12.6		MGO General Observation							occasional blistering
17.3		DAE Deposits Attached Encrustation			5	J 12 03			
18.7		SSS Surface Spalling				07 08			
20.6		CL Crack Longitudinal				J 12			
20.6		CL Crack Longitudinal				J 06			
20.8		TBI Tap Break-in Intruding	100	10		J 12			
21.3		TBI Tap Break-in Intruding	100	25		12			
21.8		DAE Deposits Attached Encrustation			5	J 09 03			
22.9		DAE Deposits Attached Encrustation			10	J 09 03			
26.6		DAE Deposits Attached Encrustation			10	J 09 03			
27.8		DAE Deposits Attached Encrustation			10	J 08 04			
31.3		DAE Deposits Attached Encrustation			15	J 07 04			
31.4		CS Crack Spiral				J 11 12			
36.9		DAE Deposits Attached Encrustation			5	J 07 10			
38.1		DAE Deposits Attached Encrustation			15	J 07 04			
38.5		MMC Material change							PVC
38.6		JOM Joint Offset Medium							
40.4		MGO General Observation							appears that a pvc pipe s ins...
40.6		TS Tap Saddle	100			J 12			



PipeLogix Inc.
 Phone: 866-299-3150
 Fax: 760-406-6023

Tabular Report of PSR 8823

for City of Saskatoon

Setup	47	Surveyor	AP	Certificate #	U-0620-70309622	System Owner	C of S
Drainage	Survey Customer C of S						
P/O #		Date	2022/11/25	Time	10:40	Street	█ Kirk Cres
City	Saskatoon	Further location details:					
Up	7747	Rim to invert		Grade to invert		Rim to grade	M
Down	3089	Rim to invert		Grade to invert		Rim to grade	M
Use	Sanitary	Direction	Down	Flow control		Media No	
Shape	Circular	Height	200	Width	mm	Preclean J	Date Cleaned
Material	Clay Tile	Joint length	M	Total length	86.0 M	Length Surveyec	108.0 M
Lining		Year laid	1960	Year rehabilitatec		Weather	
Purpose		Cat				Pressure	
Additional info	Counter reading 108m Should be 86m.					Structural	O & M
Location						Miscellaneous	Constructional
Project	Sanitary CCTV					Work Order	
Northing	Easting					Elevation	
Coordinate System	GPS Accuracy						

Count	Video	CD Code		In1	In2	%	JntFr	To	ImRef	Remarks
41.5			TSA Tap Saddle Active	100			12			
41.9			MMC Material change							VCT
63.2		S01	FM Fracture Multiple				J 12	12		
64.4		F01	FM Fracture Multiple				J 12	12		
64.4			MMC Material change							PVC
64.7			TS Tap Saddle	100			12			
65.0			TSA Tap Saddle Active	100			12			
67.2			MMC Material change							VCT
67.2			MWL Water Level			20				
69.2			MWL Water Level			10				
84.2			DAE Deposits Attached Encrustation			5	J 08	04		
87.0			FM Fracture Multiple				J 11	11		
87.2			TBI Tap Break-in Intruding	100	10		J 10			
87.4			TB Tap Break-in	100			01			
93.9			MWL Water Level			20				
94.4			MWL Water Level			30				
96.7			MWL Water Level			20				
102.2			MWL Water Level			10				
107.5			FM Fracture Multiple				J 12	12		
107.5			B Broken				J 10	02		
108.0			AMH Manhole							3089
108.0			FH End of Survey							

108.0 M Total Length Surveyed

Scores	Structural:	Pipe Rating	Pipe Ratings Inde>	Quick Rating
	O&M:	Pipe Rating	Pipe Ratings Inde>	Quick Rating
	Overall	Pipe Rating	Pipe Ratings Inde>	Quick Rating



PipeLogix Inc.
 Phone:866-299-3150
 Fax:760-406-6023

Tabular Report of PSR 8824

for City of Saskatoon

Setup	58	Surveyor	HT	Certificate #	U-915-070R00267	System Owner	City of Saskatoon
Drainage	Survey Customer: City of Saskatoon						
P/O #	Date	2022/12/12	Time	15:22	Street	Kirk Cr	
City	Saskatoon	Further location details					
Up	7746	Rim to invert	Grade to invert	Rim to grade	M		
Down	7747	Rim to invert	Grade to invert	Rim to grade	M		
Use	Sanitary	Direction	Down	Flow control	De-Watered using J	Media No	
Shape	Circular	Height	200	Width	mm	Preclean J	Date Cleaned 2022/12/09
Material	Clay Tile	Joint length	M	Total length	82.0	M	Length Surveyec 60.2 M
Lining		Year laid	1960	Year rehabilitatec		Weather	
Purpose	Routine Assessment	Cat		Pressure			
Additional info				Structural O & M Constructional Miscellaneous			
Location				Work Order			
Project 22-0375				Elevation			
Northing				Easting			
Coordinate System				GPS Accuracy			

Count	Video	CD Code	In1	In2	%	JntFr	To	ImRef	Remarks
0.0		ST Start of Survey							
0.0		AMH Manhole							7746
0.0		MWL Water Level			0				
0.3		B Broken				J 11 07			
2.3		CM Crack Multiple				J 12 12			
2.5		TB Tap Break-in	100			11			
2.9		TB Tap Break-in	100			01			
3.2		MWL Water Level			5				
3.9		MGO General Observation							occasional blistering
19.2		TB Tap Break-in	100			11			
19.6		CM Crack Multiple				J 12 02			
19.7		TB Tap Break-in	100			J 01			
35.3		CS Crack Spiral				10 12			
35.4		TB Tap Break-in	100			J 10			
35.7		CM Crack Multiple				J 01 02			
35.9		TB Tap Break-in	100			01			
50.8		CM Crack Multiple				J 11 12			
50.9		TBA Tap Break-in Active	100			12			
51.4		TBA Tap Break-in Active	100			12			
54.3		MWL Water Level			20				
54.7		MWL Water Level			40				
57.8		MWL Water Level			30				
59.1		MWL Water Level			10				
60.2		MSA Abandoned Survey							OFSET

60.2 M Total Length Surveyed

Scores	Structural:	Pipe Rating	Pipe Ratings Inde)	Quick Rating
	O&M:	Pipe Rating	Pipe Ratings Inde)	Quick Rating
	Overall	Pipe Rating	Pipe Ratings Inde)	Quick Rating



PipeLogix Inc.
 Phone:866-299-3150
 Fax:760-406-6023

Tabular Report of PSR 8825

for City of Saskatoon

Setup	57	Surveyor	HT	Certificate #	U-915-070R00267	System Owner	City of Saskatoon
Drainage	Survey Customer City of Saskatoon						
P/O #		Date	2022/12/12	Time	13:26	Street	█ Kirk Cr
City	Saskatoon	Further location detail:					
Up	7741	Rim to invert		Grade to invert		Rim to grade	M
Down	7746	Rim to invert		Grade to invert		Rim to grade	M
Use	Sanitary	Direction	Down	Flow control	De-Watered using J	Media No	
Shape	Circular	Height	200	Width	mm	Preclean J	Date Cleaned 2022/12/09
Material	Clay Tile	Joint length	M	Total length	88.6 M	Length Surveyed	88.0 M
Lining		Year laid	1960	Year rehabilitated		Weather	
Purpose	Routine Assessment	Cat		Pressure			
Additional info						Structural	O & M
Location						Miscellaneous	Constructional
Project	22-0375	Work Order					
Northing		Easting				Elevation	
Coordinate System				GPS Accuracy			

Count	Video	CD	Code	In1	In2	%	JntFr	To	Im Ref	Remarks
0.0			ST Start of Survey							
0.0			AMH Manhole							7741
0.0			MWL Water Level			0				
0.0			CM Crack Multiple				J 04	09		
1.4			CS Crack Spiral				J 12	01		
2.1			MGO General Observation							occasional blister
2.7			CL Crack Longitudinal				J 02			
4.6			TB Tap Break-in	100				10		
4.6			FM Fracture Multiple					12 12		
7.0			CL Crack Longitudinal				J 02			
8.7			MMC Material change							PVC
9.8			MWL Water Level			5				
10.5			MMC Material change							VCP
12.4			RFJ Roots Fine Joint				J 09			
13.5			RFJ Roots Fine Joint				J 02	03		
14.6			CL Crack Longitudinal				J 02			
14.7			RFC Roots Fine Connection					08 09		
14.7			FM Fracture Multiple				J 10	09		
14.8			TB Tap Break-in	100				10		
18.1			MWL Water Level			10				
24.7			CM Crack Multiple					01 02		
25.0			TB Tap Break-in	100				02		
25.0			RFC Roots Fine Connection					03		
25.3			RFJ Roots Fine Joint				J 12			
25.5			CM Crack Multiple				J 07	09		
25.5			DAE Deposits Attached Encrustation			50		08 10		in lateral
25.6			TBD Tap Break-in Defective	100				10		calcium in lateral
28.5			RFJ Roots Fine Joint				J 11	12		
29.6			RFJ Roots Fine Joint				J 08	01		
30.7			RFJ Roots Fine Joint				J 08	10		
31.8			RFJ Roots Fine Joint				J 08			



PipeLogix Inc.
 Phone: 866-299-3150
 Fax: 760-406-6023

Tabular Report of PSR 8825

for City of Saskatoon

Setup	57	Surveyor	HT	Certificate#	U-915-070R00267	System Owner	City of Saskatoon
Drainage	Survey Customer: City of Saskatoon						
P/O #		Date	2022/12/12	Time	13:26	Street	█ Kirk Cr
City	Saskatoon	Further location details:					
Up	7741	Rim to invert		Grade to invert		Rim to grade	M
Down	7746	Rim to invert		Grade to invert		Rim to grade	M
Use	Sanitary	Direction	Down	Flow control	De-Watered using J	Media No	
Shape	Circular	Height	200	Width	mm	Preclean	J
Material	Clay Tile	Joint length	M	Total length	88.6 M	Length Surveyed	88.0 M
Lining		Year laid	1960	Year rehabilitatec		Weather	
Purpose	Routine Assessment	Cat		Pressure			
Additional info				Structural O & M Constructional Miscellaneous			
Location				Work Order			
Project				Elevation			
Northing				GPS Accuracy			
Coordinate System							

Count	Video	CD Code	In1	In2	%	JntFr	To	ImRef	Remarks
32.8		RFJ	Roots Fine Joint			J	03	04	
33.8		RFJ	Roots Fine Joint			J	08	04	
38.3		RFJ	Roots Fine Joint			J	03	04	
39.3		RFJ	Roots Fine Joint			J	01	03	
41.7		RFC	Roots Fine Connection				09	11	
41.7		FM	Fracture Multiple			J	11	09	
41.8		TB	Tap Break-in	100			10		
42.1		CM	Crack Multiple				02	04	
42.2		RFC	Roots Fine Connection				02	03	
42.3		TB	Tap Break-in	100			02		
42.5		RFJ	Roots Fine Joint			J	04		
43.6		RFJ	Roots Fine Joint			J	09	03	
45.7		RFJ	Roots Fine Joint			J	09	10	
46.9		FM	Fracture Multiple			J	06	12	
51.1		RFJ	Roots Fine Joint			J	10	01	
51.2		CS	Crack Spiral			J	12	01	
56.5		RFJ	Roots Fine Joint			J	09	12	
57.6		RFJ	Roots Fine Joint			J	03		
58.7		FS	Fracture Spiral			J	11	01	
58.9		TB	Tap Break-in	100			02		
58.9		CM	Crack Multiple			J	12	04	
62.9		CS	Crack Spiral			J	10	11	
73.8		CL	Crack Longitudinal			J	11		
74.0		TB	Tap Break-in	100			11		
74.0		CS	Crack Spiral			J	09	10	
74.6		TB	Tap Break-in	100			01		
74.9		B	Broken			J	02	05	
87.8		B	Broken			J	02	10	
88.0		AMH	Manhole						7746
88.0		FH	End of Survey						

88.0 M Total Length Surveyed



PipeLogix Inc.
 Phone:866-299-3150
 Fax:760-406-6023

Tabular Report of PSR 8825

for **City of Saskatoon**

Setup 57	Surveyor HT	Certificate# U-915-070R00267	System Owner City of Saskatoon
Drainage	Survey Customer City of Saskatoon		
P/O #	Date 2022/12/12	Time 13:26	Street █ Kirk Cr
City Saskatoon	Further location details		
Up 7741	Rim to invert	Grade to invert	Rim to grade M
Down 7746	Rim to invert	Grade to invert	Rim to grade M
Use Sanitary	Direction Down	Flow control De-Watered using J	Media No
Shape Circular	Height 200	Width mm	Preclean J
Material Clay Tile	Joint length M	Total length 88.6 M	Date Cleaned 2022/12/09
Lining	Year laid 1960	Year rehabilitatec	Length Surveyec 88.0 M
Purpose Routine Assessment	Cat	Weather	Pressure
Additional info		Structural	O & M
Location		Constructional	
Project 22-0375	Miscellaneous		
Northing	Easting	Work Order	
Coordinate System		Elevation	
		GPS Accuracy	

Scores	Structural:	Pipe Rating	Pipe Ratings Inde>	Quick Rating
	O&M:	Pipe Rating	Pipe Ratings Inde>	Quick Rating
	Overall	Pipe Rating	Pipe Ratings Inde>	Quick Rating



PipeLogix Inc.
Phone:866-299-3150
Fax:760-406-6023

Tabular Report of PSR 8834

for City of Saskatoon

Setup	56	Surveyor	HT	Certificate#	U-915-070R00267	System Owner	City of Saskatoon
Drainage		Survey Customer	City of Saskatoon				
P/O #		Date	2022/12/12	Time	12:44	Street	█ Kirk Cr
City	Saskatoon	Further location details					
Up	7741	Rim to invert		Grade to invert		Rim to grade	M
Down	7743	Rim to invert		Grade to invert		Rim to grade	M
Use	Sanitary	Direction	Down	Flow control	De-Watered using J	Media No	
Shape	Circular	Height	200	Width	mm	Preclean J	Date Cleaned 2022/12/09
Material	Clay Tile	Joint length	M	Total length	43.7 M	Length Surveyed	42.7 M
Lining		Year laid	1960	Year rehabilitate		Weather	
Purpose	Routine Assessment	Cat				Pressure	
Additional info						Structural	O & M
Location						Miscellaneous	Constructional
Project	22-0375	Easting				Work Order	
Northing						Elevation	
Coordinate System						GPS Accuracy	

Count	Video	CD	Code	In1	In2	%	JntFr	To	ImRef	Remarks
0.0			ST Start of Survey							
0.0			AMH Manhole							7741
0.0			MWL Water Level			0				
0.0			CM Crack Multiple				J 11	01		
0.6			CM Crack Multiple				J 12	09		
0.9			RFC Roots Fine Connection					02 03		
1.0			TB Tap Break-in	100				02		
1.0			CM Crack Multiple					02 01		
2.8			RFJ Roots Fine Joint				J 07	04		
3.3			MGO General Observation							occasional blister
3.6			RFJ Roots Fine Joint				J 09	04		
4.3			RFJ Roots Fine Joint				J 12	08		
5.4			CM Crack Multiple				J 07	12		
11.7			CS Crack Spiral				J 01	02		
12.9			RFJ Roots Fine Joint				J 01	02		
13.5			RFC Roots Fine Connection					01 03		
13.6			TB Tap Break-in	100				02		
15.0			RFJ Roots Fine Joint				J 08	02		
16.1			RFJ Roots Fine Joint				J 09	01		
17.2			RFJ Roots Fine Joint				J 08	03		
19.4			RFJ Roots Fine Joint				J 10	12		
20.5			RFJ Roots Fine Joint				J 09	02		
22.5			RFJ Roots Fine Joint				J 12	04		
26.9			RFJ Roots Fine Joint				J 08	03		
29.0			RFJ Roots Fine Joint				J 12			
30.1			RFJ Roots Fine Joint				J 08	09		
30.3			RFC Roots Fine Connection					01 02		
30.4			TB Tap Break-in	100				02		
31.1			RFJ Roots Fine Joint				J 09	10		
32.2			RFJ Roots Fine Joint				J 08	03		
34.4			RFJ Roots Fine Joint				J 08			



PipeLogix Inc.
 Phone: 866-299-3150
 Fax: 760-406-6023

Tabular Report of PSR 8834

for City of Saskatoon

Setup	56	Surveyor	HT	Certificate #	U-915-070R00267	System Owner	City of Saskatoon
Drainage	Survey Customer: City of Saskatoon						
P/O #		Date	2022/12/12	Time	12:44	Street	█ Kirk Cr
City	Saskatoon	Further location detail:					
Up	7741	Rim to invert		Grade to invert		Rim to grade	M
Down	7743	Rim to invert		Grade to invert		Rim to grade	M
Use	Sanitary	Direction	Down	Flow control	De-Watered using J	Media No	
Shape	Circular	Height	200	Width	mm	Preclean J	Date Cleaned 2022/12/09
Material	Clay Tile	Joint length	M	Total length	43.7 M	Length Surveyed	42.7 M
Lining		Year laid	1960	Year rehabilitate		Weather	
Purpose	Routine Assessment	Cat		Pressure			

Additional info	Structural	O & M	Constructional
Location	Miscellaneous		
Project	22-0375	Work Order	
Northing		Easting	Elevation
Coordinate System		GPS Accuracy	

Count	Video	CD	Code	In1	In2	%	JntFr	To	ImRef	Remarks
35.4			RFJ Roots Fine Joint				J 09 10			
36.5			RFJ Roots Fine Joint				J 12 02			
39.8			RFJ Roots Fine Joint				J 09 03			
41.9			RFJ Roots Fine Joint				J 08 03			
42.7			AMH Manhole							7743
42.7			FH End of Survey							

42.7 M Total Length Surveyed

Scores	Structural:	Pipe Rating	Pipe Ratings Inde>	Quick Rating
	O&M:	Pipe Rating	Pipe Ratings Inde>	Quick Rating
	Overall	Pipe Rating	Pipe Ratings Inde>	Quick Rating



PipeLogix Inc.
 Phone:866-299-3150
 Fax:760-406-6023

Tabular Report of PSR 8833

for City of Saskatoon

Setup	55	Surveyor	HT	Certificate #	U-915-070R00267	System Owner	City of Saskatoon
Drainage		Survey Customer	City of Saskatoon				
P/O #		Date	2022/12/12	Time	12:03	Street	█ Kirk Cr
City	Saskatoon	Further location detail:					
Up	7742	Rim to invert		Grade to invert		Rim to grade	M
Down	7743	Rim to invert		Grade to invert		Rim to grade	M
Use	Sanitary	Direction	Down	Flow control	De-Watered using J	Media No	
Shape	Circular	Height	200	Width	mm	Preclean J	Date Cleaned 2022/12/09
Material	Clay Tile	Joint length	M	Total length	40.0 M	Length Surveyed	40.0 M
Lining		Year laid	1960	Year rehabilitated		Weather	
Purpose	Routine Assessment	Cat				Pressure	
Additional info						Structural	O & M
Location						Miscellaneous	Constructional
Project	22-0375	Easting				Work Order	
Northing		Elevation				GPS Accuracy	
Coordinate System				GPS Accuracy			

Count	Video	CD Code	In1	In2	%	JntFr	To	ImRef	Remarks
0.0		ST	Start of Survey						
0.0		AMH	Manhole						7742
0.0		MWL	Water Level		0				
0.0		CS	Crack Spiral			J	06	07	
0.1		CS	Crack Spiral			J	05	06	
0.1		CS	Crack Spiral			J	01	05	
0.6		FS	Fracture Spiral			J	09	12	
0.6		RFJ	Roots Fine Joint			J	08	09	
0.9		TB	Tap Break-in	100			10		
0.9		RFC	Roots Fine Connection				09	10	
1.0		FS	Fracture Spiral				01	09	
1.0		CS	Crack Spiral				10	11	
1.7		RFJ	Roots Fine Joint			J	10		
6.0		RFJ	Roots Fine Joint			J	02		
13.1		RFC	Roots Fine Connection				07	10	
13.2		TB	Tap Break-in	100			10		
23.2		RFJ	Roots Fine Joint			J	09	10	
28.6		RFJ	Roots Fine Joint			J	09	02	
29.6		RFJ	Roots Fine Joint			J	09	11	
30.2		TB	Tap Break-in	100			10		
30.2		RFC	Roots Fine Connection				09	12	
30.6		MWL	Water Level		5				
30.7		RFJ	Roots Fine Joint			J	09	02	
32.7		CL	Crack Longitudinal				12		
32.9		RFJ	Roots Fine Joint			J	01	03	
34.0		CL	Crack Longitudinal			J	08		
36.1		RFJ	Roots Fine Joint			J	09	03	
36.8		MWL	Water Level		10				
37.2		RFJ	Roots Fine Joint			J	10	03	
37.2		RFJ	Roots Fine Joint			J	10	03	
38.3		MWL	Water Level		20				



PipeLogix Inc.
 Phone: 866-299-3150
 Fax: 760-406-6023

Tabular Report of PSR 8833

for **City of Saskatoon**

Setup 55	Surveyor HT	Certificate # U-915-070R00267	System Owner City of Saskatoon
Drainage		Survey Customer City of Saskatoon	
P/O #	Date 2022/12/12	Time 12:03	Street █ Kirk Cr
City Saskatoon	Further location details:		
Up 7742	Rim to invert	Grade to invert	Rim to grade M
Down 7743	Rim to invert	Grade to invert	Rim to grade M
Use Sanitary	Direction Down	Flow control De-Watered using J	Media No
Shape Circular	Height 200	Width mm	Preclean J
Material Clay Tile	Joint length M	Total length 40.0 M	Length Surveyed 40.0 M
Lining	Year laid 1960	Year rehabilitated	Weather
Purpose Routine Assessment	Cat	Pressure	
Additional info		Structural	O & M
Location		Miscellaneous	Constructional
Project 22-0375	Work Order		
Northing	Easting	Elevation	
Coordinate System		GPS Accuracy	

Count	Video	CD	Code	In1	In2	%	JntFr	To	ImRef	Remarks
39.4			RFJ	Roots Fine Joint			J	08	04	
40.0			AMH	Manhole						7743
40.0			FH	End of Survey						

40.0 M Total Length Surveyed

Scores	Structural:	Pipe Rating	Pipe Ratings Index	Quick Rating
	O&M:	Pipe Rating	Pipe Ratings Index	Quick Rating
	Overall:	Pipe Rating	Pipe Ratings Index	Quick Rating



PipeLogix Inc.
 Phone: 866-299-3150
 Fax: 760-406-6023

Tabular Report of PSR 8828

for City of Saskatoon

Setup 54	Surveyor HT	Certificate # U-915-070R00267	System Owner City of Saskatoon
Drainage	Survey Customer City of Saskatoon		
P/O #	Date 2022/12/09	Time 11:27	Street █ Kirk Cr
City Saskatoon	Further location details:		
Up 3092	Rim to invert	Grade to invert	Rim to grade M
Down 7742	Rim to invert	Grade to invert	Rim to grade M
Use Sanitary	Direction Down	Flow control De-Watered using J	Media No
Shape Circular	Height 200	Width mm	Preclean J
Material Clay Tile	Joint length M	Total length 94.8 M	Length Surveyed 94.9 M
Lining	Year laid 1960	Year rehabilitated	Weather
Purpose Routine Assessment	Cat	Pressure	
Additional info		Structural	O & M
Location		Miscellaneous	Constructional
Project 22-0375	Work Order		
Northing	Easting	Elevation	
Coordinate System	GPS Accuracy		

Count	Video	CD	Code	In1	In2	%	JntFr	To	ImRef	Remarks
0.0			ST Start of Survey							
0.0			AMH Manhole							3092
0.0			MWL Water Level			5				
0.3			FC Fracture Circumferential					12	12	
0.5			MGO General Observation							occasional blisters
1.1			RFJ Roots Fine Joint				J	07	04	
1.5			TB Tap Break-in	100				02		
1.5			RFC Roots Fine Connection					01	03	
1.8			RFC Roots Fine Connection					09	11	
1.9			TB Tap Break-in	100				10		
2.2		S01	RFJ Roots Fine Joint				J	07	03	
10.8		F01	RFJ Roots Fine Joint				J	07	03	
15.1			RFJ Roots Fine Joint				J	08	01	
17.3			RFJ Roots Fine Joint				J	08	04	
18.6			TB Tap Break-in	100				02		
18.6			RFC Roots Fine Connection					03		
18.8			RMC Roots Medium Connection			40		07	10	
18.9			TBD Tap Break-in Defective	100				10		
19.4			RFJ Roots Fine Joint				J	08	02	
35.2			TB Tap Break-in	100				10		
35.5			CL Crack Longitudinal				J	02		
35.8			HSV Hole Soil Visible					01	02	
35.9			TB Tap Break-in	100				02		
51.4			TB Tap Break-in	100				10		
51.4			CL Crack Longitudinal					10		
52.3			TB Tap Break-in	100				02		
52.3			RFC Roots Fine Connection					03		
61.4			RFJ Roots Fine Joint				J	09	03	
62.5			RFJ Roots Fine Joint				J	10	12	
64.7			RFJ Roots Fine Joint				J	01	02	
65.7			RFJ Roots Fine Joint				J	09	10	



PipeLogix Inc.
 Phone: 866-299-3150
 Fax: 760-406-6023

Tabular Report of PSR 8828

for City of Saskatoon

Setup	54	Surveyor	HT	Certificate#	U-915-070R00267	System Owner	City of Saskatoon
Drainage	Survey Customer: City of Saskatoon						
P/O #	Date	2022/12/09	Time	11:27	Street	█	Kirk Cr
City	Saskatoon	Further location details					
Up	3092	Rim to invert	Grade to invert	Rim to grade	M		
Down	7742	Rim to invert	Grade to invert	Rim to grade	M		
Use	Sanitary	Direction	Down	Flow control	De-Watered using J	Media No	
Shape	Circular	Height	200	Width	mm	Preclean	J
Material	Clay Tile	Joint length	M	Total length	94.8	M	Length Surveyec
Lining		Year laid	1960	Year rehabilitatec		Weather	
Purpose	Routine Assessment	Cat		Pressure			
Additional info				Structural	O & M	Constructional	
Location				Miscellaneous			
Project	22-0375			Work Order			
Northing		Easting		Elevation			
Coordinate System				GPS Accuracy			

Count	Video	CD Code	In1	In2	%	JntFr	To	ImRef	Remarks
67.9		RFJ				J 11 03			Roots Fine Joint
69.2		TBD	100			10			Tap Break-in Defective
69.2		RFC				09 11			Roots Fine Connection
69.6		TBD	100			02			Tap Break-in Defective
69.6		RFC				01 03			Roots Fine Connection
70.1		RFJ				J 09 03			Roots Fine Joint
70.1		CS				J 09 12			Crack Spiral
70.7		TB	100			03			Tap Break-in
70.7		RFC				01 03			Roots Fine Connection
71.2		RFJ				J 09 03			Roots Fine Joint
73.6		RFJ				J 09 01			Roots Fine Joint
76.9		TB	100			10			Tap Break-in
76.9		RFC				10 11			Roots Fine Connection
78.7		RFJ				J 12 04			Roots Fine Joint
79.7		RFJ				J 09 10			Roots Fine Joint
82.0		RFJ				J 09 01			Roots Fine Joint
84.1		RFJ				J 08 03			Roots Fine Joint
84.1		FM				J 09 02			Fracture Multiple
84.8		S02			50				MMLS Water Level Sag
86.1		F02			50				MMLS Water Level Sag
87.2		RFJ				J 09 03			Roots Fine Joint
87.2		FM				J 10 02			Fracture Multiple
92.2		RFC				09 10			Roots Fine Connection
92.3		TB	100			10			Tap Break-in
93.8		RFJ				J 02 03			Roots Fine Joint
94.5		FS				02 11			Fracture Spiral
94.9		AMH							Manhole
94.9		FH							End of Survey

94.9 M Total Length Surveyed



PipeLogix Inc.
 Phone: 866-299-3150
 Fax: 760-406-6023

Tabular Report of PSR 8828

for **City of Saskatoon**

Setup 54	Surveyor HT	Certificate # U-915-070R00267	System Owner City of Saskatoon
Drainage		Survey Customer City of Saskatoon	
P/O #	Date 2022/12/09	Time 11:27	Street █ Kirk Cr
City Saskatoon	Further location details:		
Up 3092	Rim to invert	Grade to invert	Rim to grade M
Down 7742	Rim to invert	Grade to invert	Rim to grade M
Use Sanitary	Direction Down	Flow control De-Watered using J	Media No
Shape Circular	Height 200	Width mm	Preclean J
Material Clay Tile	Joint length M	Total length 94.8 M	Length Surveyed 94.9 M
Lining	Year laid 1960	Year rehabilitatec	Weather
Purpose Routine Assessment	Cat	Pressure	
Additional info		Structural	O & M
Location		Miscellaneous	Constructional
Project 22-0375	Work Order		
Northing	Easting	Elevation	
Coordinate System	GPS Accuracy		

Scores	Structural: Pipe Rating	Pipe Ratings Inde>	Quick Rating
	O&M: Pipe Rating	Pipe Ratings Inde>	Quick Rating
	Overall Pipe Rating	Pipe Ratings Inde>	Quick Rating



PipeLogix Inc.
Phone:866-299-3150
Fax:760-406-6023

Tabular Report of PSR 8827

for City of Saskatoon

Setup	53	Surveyor	HT	Certificate#	U-915-070R00267	System Owner	City of Saskatoon
Drainage		Survey Customer	City of Saskatoon				
P/O #		Date	2022/12/09	Time	10:30	Street	█ Kirk Cr
City	Saskatoon	Further location details:					
Up	3093	Rim to invert		Grade to invert		Rim to grade	M
Down	3092	Rim to invert		Grade to invert		Rim to grade	M
Use	Sanitary	Direction	Down	Flow control	De-Watered using J	Media No	
Shape	Circular	Height	200	Width	mm	Preclean	J
Material	Clay Tile	Joint length	M	Total length	95.6 M	Length Surveye	141.8 M
Lining		Year laid		Year rehabilitate		Weather	
Purpose	Routine Assessment	Cat		Pressure			
Additional info	This section is 96.6m long not 140m					Structural	O & M
Location					Miscellaneous	Constructional	
Project	22-0375					Work Order	
Northing		Easting				Elevation	
Coordinate System						GPS Accuracy	

Count	Video	CD	Code	In1	In2	%	JntFr	To	ImRef	Remarks
0.0			ST Start of Survey							
0.0			AMH Manhole							3093
0.0			MWL Water Level			0				
0.0			FM Fracture Multiple				J 09	01		
0.1			B Broken				J 09	09		
0.9			B Broken				J 09	01		
4.9			MWL Water Level			5				
7.9			RFC Roots Fine Connection				01	02		
8.0			TB Tap Break-in	100			01			
9.7			CL Crack Longitudinal				J 10			
9.9			TB Tap Break-in	100			J 10			
10.4			TB Tap Break-in	100			02			
13.8			CL Crack Longitudinal				J 07			
31.0			TB Tap Break-in	100			01			
31.1			RFC Roots Fine Connection				01	02		
31.5			RFC Roots Fine Connection				08	11		
31.5			ISSRH Intruding Sealing Ring Hanging			5	08	12		
31.6			TS Tap Saddle	100			09			
57.4			CS Crack Spiral				03	09		
59.7			CM Crack Multiple				J 02	08		
59.7			SSS Surface Spalling				J 01	02		
60.0			TB Tap Break-in	100			J 01			
60.0			RFC Roots Fine Connection				12	02		
60.2			FS Fracture Spiral				12	12		
60.6			TBD Tap Break-in Defective	100			10			
60.6			RBL Roots Ball Lateral			100	10	11		
60.7			RFC Roots Fine Connection				09	10		
82.2			RFC Roots Fine Joint				J 12			
90.3			FS Fracture Spiral				J 01	02		
90.5			TB Tap Break-in	100			J 01			
90.5			RFC Roots Fine Connection				12	01		



PipeLogix Inc.
 Phone: 866-299-3150
 Fax: 760-406-6023

Tabular Report of PSR 8827

for City of Saskatoon

Setup	53	Surveyor	HT	Certificate #	U-915-070R00267	System Owner	City of Saskatoon
Drainage	Survey Customer City of Saskatoon						
P/O #		Date	2022/12/09	Time	10:30	Street	█ Kirk Cr
City	Saskatoon	Further location details:					
Up	3093	Rim to invert		Grade to invert		Rim to grade	M
Down	3092	Rim to invert		Grade to invert		Rim to grade	M
Use	Sanitary	Direction	Down	Flow control	De-Watered using J	Media No	
Shape	Circular	Height	200	Width	mm	Preclean J	Date Cleaned 2022/12/09
Material	Clay Tile	Joint length	M	Total length	95.6 M	Length Surveyec	141.8 M
Lining		Year laid		Year rehabilitatec		Weather	
Purpose	Routine Assessment	Cat				Pressure	
Additional info	This section is 96.6m long not 140m					Structural	O & M
Location						Miscellaneous	Constructional
Project	22-0375	Easting			Work Order		
Northing					Elevation		
Coordinate System					GPS Accuracy		

Count	Video	CD	Code	In1	In2	%	Jnt	Fr	To	Im	Ref	Remarks
90.7			FS	Fracture Spiral					01	09		
91.1			TBD	Tap Break-in Defective	100				10			
91.1			RFC	Roots Fine Connection					07	12		
113.6			MWL	Water Level		10						
114.2			TB	Tap Break-in	100				02			
114.6			TB	Tap Break-in	100				10			
115.3			FM	Fracture Multiple			J	12	06			
121.7			RFJ	Roots Fine Joint			J	09	02			
123.1			RFJ	Roots Fine Joint			J	09	10			
124.7			RFJ	Roots Fine Joint			J	08	04			
125.2			TS	Tap Saddle	100				09			
127.7			RFJ	Roots Fine Joint			J	09	03			
129.1			RFJ	Roots Fine Joint			J	08	04			
129.4			MWL	Water Level		20						
130.6			RFJ	Roots Fine Joint			J	08	11			
138.3			RFJ	Roots Fine Joint			J	08	04			
141.3			RFJ	Roots Fine Joint			J	08	04			
141.8			AMH	Manhole								3092
141.8			FH	End of Survey								

141.8 M Total Length Surveyed

Scores	Structural:	Pipe Rating	Pipe Ratings Inde>	Quick Rating
	O&M:	Pipe Rating	Pipe Ratings Inde>	Quick Rating
	Overall	Pipe Rating	Pipe Ratings Inde>	Quick Rating



PipeLogix Inc.
 Phone: 866-299-3150
 Fax: 760-406-6023

Tabular Report of PSR 8826

for City of Saskatoon

Setup	51	Surveyor	AP	Certificate#	U-0620-70309622	System Owner	
Drainage		Survey Customer	C of S				
P/O #		Date	2022/11/25	Time	13:26	Street	█ Kirk Cr
City	Saskatoon	Further location details:					
Up	3088	Rim to invert		Grade to invert		Rim to grade	M
Down	3093	Rim to invert		Grade to invert		Rim to grade	M
Use	Sanitary	Direction	Down	Flow control	De-Watered using J	Media No	
Shape	Circular	Height	200	Width	mm	Preclean J	Date Cleaned 2022/11/25
Material	Clay Tile	Joint length	M	Total length	103.0 M	Length Surveyed	103.0 M
Lining		Year laid	1960	Year rehabilitate	c	Weather	
Purpose		Cat				Pressure	
Additional info						Structural	O & M
Location						Miscellaneous	Constructional
Project	Sanitary CCTV					Work Order	
Northing		Easting				Elevation	
Coordinate System						GPS Accuracy	

Count	Video	CD Code	In1	In2	%	JntFr	To	ImRef	Remarks
0.0		CM Crack Multiple				J 11 06			
0.0		ST Start of Survey							
0.0		AMH Manhole							3088
0.0		MWL Water Level			0				
0.5		HSV Hole Soil Visible				04 05			
0.5		B Broken				02 09			
0.6		FC Fracture Circumferential				07 04			
0.6		CM Crack Multiple				08 04			
0.9		B Broken				J 12 01			
13.5		TB Tap Break-in	100			10			
34.7		CM Crack Multiple				J 09 10			
34.9		TB Tap Break-in	100			10			
53.6		TB Tap Break-in	100			11			
54.2		CL Crack Longitudinal				J 10			
55.1		DAE Deposits Attached Encrustation			10	J 07 05			
57.0		CM Crack Multiple				J 05 06			
71.4		TB Tap Break-in	100			12			
89.5		TB Tap Break-in	100			11			
93.1		RFJ Roots Fine Joint				J 05 08			
97.2		RFJ Roots Fine Joint				J 09 04			
102.2		HSV Hole Soil Visible				J 08 02			
103.0		MSA Abandoned Survey							offset

103.0 M Total Length Surveyed

Scores	Structural:	Pipe Rating	Pipe Ratings Inde)	Quick Rating
	O&M:	Pipe Rating	Pipe Ratings Inde)	Quick Rating
	Overall	Pipe Rating	Pipe Ratings Inde)	Quick Rating



PipeLogix Inc.
 Phone:866-299-3150
 Fax:760-406-6023

Tabular Report of PSR 8830

for City of Saskatoon

Setup	49	Surveyor	AP	Certificate#	U-0620-70309622	System Owner	
Drainage		Survey Customer	C of S				
P/O #		Date	2022/11/25	Time	12:24	Street	Kirk Cr
City	Saskatoon	Further location details:					
Up	3089	Rim to invert		Grade to invert		Rim to grade	M
Down	3088	Rim to invert		Grade to invert		Rim to grade	M
Use	Sanitary	Direction	Down	Flow control	De-Watered using J	Media No	
Shape	Circular	Height	200	Width	mm	Preclean J	Date Cleaned 2022/11/25
Material	Clay Tile	Joint length	M	Total length	84.3 M	Length Surveyec	82.8 M
Lining		Year laid	1960	Year rehabilitated		Weather	
Purpose		Cat				Pressure	
Additional info		Structural		O & M		Constructional	
Location		Miscellaneous					
Project	Sanitary CCTV	Work Order					
Northing		Easting		Elevation			
Coordinate System		GPS Accuracy					

Count	Video	CD	Code	In1	In2	%	JntFr	To	ImRef	Remarks
0.0			CM Crack Multiple				J 12 12			
0.0			ST Start of Survey							
0.0			AMH Manhole							3089
0.0			MWL Water Level			5				
0.4			FM Fracture Multiple				J 12 12			
0.7			B Broken				J 04 09			
0.9			FS Fracture Spiral				J 09 04			
2.2			MWL Water Level			10				
2.4			MGO General Observation							occasional blisters
3.5			MWL Water Level			20				
4.8			MWL Water Level			30				
4.9			MWL Water Level			40				
6.0			MWL Water Level			30				
8.8			MWL Water Level			50				
9.1			MCU Camera Underwater							
9.7			MWL Water Level			50				
9.9			MWL Water Level			30				
11.3			MWL Water Level			40				
11.9			MWL Water Level			30				
12.3			MWL Water Level			10				
13.2			MWL Water Level			20				
13.5			MWL Water Level			30				
13.9			MWL Water Level			40				
14.5			MWL Water Level			50				
14.9			MCU Camera Underwater							
16.1			MWL Water Level			40				
16.2			MWL Water Level			20				
16.7			MWL Water Level			10				
16.9			DAE Deposits Attached Encrustation			10	J 08 03			
19.0			DAE Deposits Attached Encrustation			10	J 07 12			
27.6			DAE Deposits Attached Encrustation			10	J 08 04			



PipeLogix Inc.
 Phone: 866-299-3150
 Fax: 760-406-6023

Tabular Report of PSR 8830

for City of Saskatoon

Setup	49	Surveyor	AP	Certificate#	U-0620-70309622	System Owner	
Drainage		Survey Customer	C of S				
P/O #		Date	2022/11/25	Time	12:24	Street	Kirk Cr
City	Saskatoon	Further location details					
Up	3089	Rim to invert		Grade to invert		Rim to grade	M
Down	3088	Rim to invert		Grade to invert		Rim to grade	M
Use	Sanitary	Direction	Down	Flow control	De-Watered using J	Media No	
Shape	Circular	Height	200	Width	mm	Preclean J	Date Cleaned 2022/11/25
Material	Clay Tile	Joint length	M	Total length	84.3 M	Length Surveyec	82.8 M
Lining		Year laid	1960	Year rehabilitatec		Weather	
Purpose		Cat				Pressure	
Additional info						Structural	O & M
Location						Miscellaneous	Constructional
Project	Sanitary CCTV					Work Order	
Northing		Easting				Elevation	
Coordinate System						GPS Accuracy	

Count	Video	CD	Code	In1	In2	%	JntFr	To	ImRef	Remarks
39.4			DAE Deposits Attached Encrustation			5	J	08	03	
43.7			DAE Deposits Attached Encrustation			10	J	08	03	
45.8			DAE Deposits Attached Encrustation			10	J	08	01	
72.7			DAE Deposits Attached Encrustation			5	J	10	03	
74.9			DAE Deposits Attached Encrustation			5	J	08	11	
76.7			MWL Water Level			20				
77.1			DAE Deposits Attached Encrustation			5	J	09	03	
77.2			CS Crack Spiral				J	10	02	
78.7			SSS Surface Spalling					12		
78.7			MWL Water Level			30				
80.3			MWL Water Level			40				
81.0			MWL Water Level			10				
82.8			MSA Abandoned Survey							Off set

82.8 M Total Length Surveyed

Scores	Structural:	Pipe Rating	Pipe Ratings Inde>	Quick Rating
	O&M:	Pipe Rating	Pipe Ratings Inde>	Quick Rating
	Overall	Pipe Rating	Pipe Ratings Inde>	Quick Rating



PipeLogix Inc.
 Phone:866-299-3150
 Fax:760-406-6023