

Photos of CPR Building Shingle Damage

Shingle damage along lower roof section



Shingles lifting and splitting

