Date	Traffic Devices	Rationale
Prior to 2014	Yield sign on Patrick Crescent	Assign right-of-way to Muzyka Road
~February 2014	Yield sign on Patrick Crescent was replaced with a stop sign.	
June 2014	To enhance visibility of the stop sign and improve safety, an additional stop sign in a temporary median island was installed on Patrick Crescent. Temporary concrete jersey barriers were also placed on Muzyka Road to protect the fence at 131 Brace Cove.	The fence at 131 Brace Cove was damaged several times by errant vehicles.
January 2018	Checkerboard sign was installed.	Installed prior to the removal of the jersey barriers.
February 2018	Temporary concrete jersey barriers in the roadway were replaced with boulders in the boulevard.	Jersey barriers were knocked over several times and posed a hazard to the travelling public.
February 2019	Concrete jersey barriers were temporarily reinstalled in the boulevard until a permanent solution could be determined.	